

## Important Safety Notice: ISC UltraLink

### Safety Notice/Product Recall



We have received feedback from users who have discovered scenarios where the unlock button can be unintentionally depressed and the device inadvertently opened during use. Whilst there have been NO reports of accidents or injuries, we are recalling both UltraLink models (LK100/LK101), in the interest of user safety.



LK100



LK101



This recall applies to all units in circulation from the 28 February to 13 March, 2023.

Batch numbers include:

**LK100:** 168276, 168153, 166671, 167961

**LK101:** 167962, 166675, 168231, 168155, 168277

**STOP USING ANY OF THE ABOVE ITEMS IMMEDIATELY  
AND REMOVE THEM FROM SERVICE.**

We are developing modifications in order to provide an UltraLink device which will be suitable for use in the wide range of applications and industries that this product serves. We will be implementing these changes as soon as possible.

We are currently finalising our corrective action and product exchange plans, follow this link for updates on our website:

<https://www.iscwales.com/News/Product-Notices/UltraLink-Notice/>

Please accept our apologies for the inconvenience. User safety is at the core of everything that we do and remains our highest priority. We appreciate receiving feedback with any concerns relating to product safety.